

**Titan TCC Site - 7504 Pleasant Run Road - Monthly Inspections and Incident Summary
Phase One Drilling Permit - March through July 2011**

	March	April	May	June	July	August
# OF INSPECTIONS						
<i>Belcheff</i>	32	21	19	20	17	
<i>City</i>	30	20	17	13	15	
<i>VOC Air Quality Inspections</i>	30	17	15	10	2	
<i>VOC Air Quality Issues/Problems</i>	0	3	8	5	1	
<i>Other Air Quality Issues/Problems</i>	0	0	0	0	0	
<i>Average PID VOC Measurement on Pad Site*</i>	0.00	1.6**	1.9**	6.6**	5**	
<i>* measured in parts per million</i>						
INCIDENTS						
<i>Police Dispatches</i>	4	0	3	0	0	
<i>Noise Complaints</i>	40	4	11	3	2	
<i>Fire Dispatches</i>	0	0	0	0	0	
<i>Lighting Complaints</i>	1	0	0	0	0	
<i>Traffic Complaints</i>	3	3	0	0	0	
<i>Other Complaints</i>	1	0	0	0	0	
<i>Trespassing</i>	3	3	0	0	1	
<i>Documented Liquid Spills*</i>	3	0	0	0	1	
<i>Road Damage</i>	1	0	0	0	0	
<i>* all spills were contained and cleaned</i>						
VIOLATIONS						
<i>Noise</i>	1	0	0	0	0	
<i>Traffic/Truck Route</i>	3	7	0	0	0	
<i>State/Federal</i>	0	0	0	0	0	
<i>Other</i>	0	0	0	0	0	

**** All VOC readings were observed on the drilling platform. No other readings were detected either on or off of the pad site. The peak reading for July was 10 ppm and the lowest reading was 0.5 ppm. The source of the VOC's are solvents used in the drilling mud.**